



NNT Software

DLLDicom.dll patch (rel. 1.0.5.0)

Issued: January 30, 2008

Summary

Affected Software and Hardware: QR-DVT 9000 working with NNT rel. 2.11.

General Information: Since the introduction of the new NNT 2.11 software, QR-DVT 9000 secondary workstations has to be updated to new 1.0.5.0 version of DLLDicom.dll software library. This new library version has to be copied in the software working folder (typically C:\NNT).

Support: For additional details about this issue contact support@qrverona.it.

Disclaimer:

This document may not, in whole or in part, be modified, copied, reproduced, distributed, translated, stored on magnetic or optical media and published, over networks, electronic bulletin boards, web sites or other on-line services, without the express written permission of QR s.r.l. The information provided is provided "as is" without warranty of any kind.

The original version of this document has been written in English language.